



**Advisory # 2020-A-042**

**Subject: Infield Tunnel East Portal Surface Repairs**

**From:** Aviation Services


**Contact:** Andrew Payter, [Andrew.Payter@gtaa.com](mailto:Andrew.Payter@gtaa.com), 416-407-9619

**Date:** 2020-07-02

Civil road repairs are planned for the Infield Tunnel East portal ramps. This is to alleviate ride quality concerns raised by our ground handlers. This work will impact north/ south movement on the service road leading into the east portal tunnel opening. Vehicle detours are being planned over two days and are summarized below.

**North Ramp – July 07, 2020, 8:00-16:00**


T1 to T3 traffic will not be able to transit through the tunnel service road / east tunnel portal for this duration. Traffic to infield cargo is permitted to access via the South Tunnel portal entrance. Transiting traffic between the terminals shall use the terminal tail of stand roads. Please see the below map for details.



**South Ramp - July 08, 2020, 8:00-16:00**

T1 to T3 traffic will not be able to transit through the tunnel service road / east tunnel portal for this duration. Traffic to infield cargo is permitted access via the North Tunnel portal entrance. Transiting traffic between the terminals shall use the terminal tail of stand roads. Please see the below map for details.

Apron entrance AK will be restricted to Aircraft code D or smaller.



If you have any questions or concerns regarding this work, please contact Andrew Payter, [Andrew.Payter@gtaa.com](mailto:Andrew.Payter@gtaa.com)