

Advisory # 2020-A-072

Subject: Update to Approved Aircraft Power Run Locations for Winter 2020-21 Season

From: Airport Operations - Aviation Programs and Compliance

Contact: Michael Bélanger, michael.belanger@gtaa.com, 416-776-7117

Date: 2020-11-09

Please note the following changes to available engine run-up positions:

The following positions that were suspended for the Summer 2020 construction season are now available for use:

Position	Location
6	Runway 15R/33L at Juliet - Tail South
6a	Taxiway Bravo at Juliet – Tail South
16	Runway 05/23 at Hotel 2 - Tail West
17	Runway 05/23 at Hotel 4 - Tail East

Effective November 10, 2020 the following positions will be unavailable until further notice:

Position	Location
9	Runway 06R/24L between Delta 4 and Delta 6 - Tail West
10	Runway 06R/24L between Delta 3 and Delta 5 - Tail East
18	Taxiway November between Foxtrot and Echo – Tail West
19	Taxiway November between Foxtrot and Echo – Tail East

Assignment of position 20 for aircraft power runs between 0000-0659L is to be as a last resort only and kept to a minimum. Positions 6 and 6a are not approved during Runway 05/23 use.

