



Advisory # **2021-A-015**
Supersedes # **2020-A-072**

Subject: Update to Approved Aircraft Power Run Locations

From: Airport Operations - Aviation Programs and Compliance

Contact: Michael Bélanger, michael.belanger@gtaa.com, 416-776-7117

Date: 2021-04-23

Please note the following changes to available engine run-up positions:

The following positions that were suspended for the Winter 2020/21 season are now available for use:

Position	Location
6	Runway 15R/33L at Juliet – Tail South
6a	Taxiway Bravo at Juliet – Tail South
9	Runway 06R/24L between Delta 4 and Delta 6 – Tail West
10	Runway 06R/24L between Delta 3 and Delta 5 – Tail East
16	Runway 05/23 at Hotel 2 – Tail West
17	Runway 05/23 at Hotel 4 – Tail East

The following positions will be unavailable until further notice:

Position	Location
18	Taxiway November between Foxtrot and Echo – Tail West
19	Taxiway November between Foxtrot and Echo – Tail East

Assignment of Position 20 for aircraft power runs between 0000-0659L is to be as a last resort only and kept to a minimum. Positions 6 and 6a are not approved during Runway 05/23 use.

