



Advisory # 2022-A-040

Subject: Terminal 3 Apron Slab Work

From: Airport Operations, Airside Coordination

Contact: Cedric Daros, cedric.daros@gtaa.com, 416-776-5854


Date: 2022-08-31

Apron Taxilane 3 will be temporarily closed in two phases for a period of four (4) weeks each commencing on September 6, 2022 @ 0001L. The work will facilitate required concrete slab replacement. As a protection throughout, a marked and lit portable jet blast fencing will be deployed.

The Apron impacts of **Phase 1** are as follows:

- Push-back times/distances will be increased for operations inside horseshoe.
- Potential aircraft holds due to a one-in/one-out operation on Taxilane 4.
- Stands B20, B22 & C25 Closed.
- Taxilane 3 Closed between B20-C25.
- Taxilane 4 modified.
- Stand C24 Modified to maintain full Code C operations
- Inset Lighting is not available on Taxilane 3 or 4.


Impacts will be minimized as much as possible with operational planning



The Apron impacts of **Phase 2** are as follows:

- Push-back times/distances will be increased for operations inside horseshoe.
- Potential aircraft holds due to a one-in/one-out operations on Taxilane 4.
- Taxilane 3 Closed between North/South Taxilane and B20.
- Stands B18 and B19 Closed
- No Impact to Taxilane 4.
- Connecting Corridor between B18 and C31 closed.
- Inset Lighting is not available on Taxilanes 3 and 4.

Impacts will be minimized as much as possible with operational planning



Additionally, there will be several short-term closures to accommodate line painting during both phases of work.

Please be aware of non-standard aircraft and vehicle movements around Taxiway 3 and 4, and associated horseshoe.

If you have any questions or concerns regarding this work, please contact Cedric Daros at cedric.daros@gtaa.com.