



Advisory # **2023-A-019**

Subject Transborder/Preclearance Area Sterility

From: Airport Operations & Governance, Corporate Safety and Security

Contact: Richard Attenborough, Richard.Attenborough@GTAA.com, 647-616-1373

Amaury Godin, Amaury.Godin@GTAA.com, 416-573-0316

Date: 2023-06-16

To continue supporting our airline partners with sterility concerns, we install visual indicators to assist with Directive **2023 - D -003 - Security Breaches in the Transborder Designated Area.**

The GTAA remains committed to aiding and ensuring sterility is maintained during swing operations. As a result, we have installed slide signs in the arrivals corridors at the following gates;

Terminal 1 – Gates 153, 136, 132.

The sliding indicator is mounted above the keypad to confirm the lounge configuration.

Terminal 3 - B18, 19.

The sliding indicator is mounted beside the keypad to confirm the lounge configuration.

Example of Slide Sign:



The red/US Flag indicates lounge is configured to **Transborder**. Offloading passengers **cannot** be directed into the lounge.

The green/Canadian Flag indicates **Domestic** configuration. Domestic arriving passengers **can** be directed into the lounge.