



Advisory #G02-2019-A-027

Subject Repair of Culvert C198

From: Airport Development & Technical services

Contact: Alberto Valencia, alberto.valencia@gtaa.com, 416-776-3394

Date: 2019 – 06 - 28

Background: A ditch upstream of Culvert C198 located at North Service Road, 400 m east of Centre line of Taxi JE, eroded the surrounding of the pipes of this culvert and under the concrete slab supporting a water quality monitoring equipment.

The work

The repair of this culvert requires the closure of one traffic lane of North Service Road at the location of the culvert. Please drive with care and follow directions of flagging personnel. This partial closure will be from July 4 to July 19, 2019.

