



Advisory # **2020-A-036**

Subject: Temporary Suspension of Aircraft Power Runs at North Field Locations

From: Aviation Programs and Compliance

Contact: John Ventresca, john.ventresca@gtaa.com, 416-776-3579

Date: 2020-05-22

To safely facilitate the 2020 airfield construction program, a temporary suspension of aircraft power runs is required at the positions outlined in the table below (per the Ground Operations Manual Section D.6.18) until approximately August 04, 2020:

Position	Location
6	Runway 33L at Juliet – Tail South
6a	Taxiway Bravo at Juliet – Tail South
16	Runway 05/23 at Hotel 2 – Tail West
17	Runway 05/23 at Hotel 4 – Tail East
18 & 19	Remain closed

Assignment of positions 9, 10, and 20 for aircraft power runs between 0000-0659L is to be as a last resort only and kept to a minimum.

