



Advisory # **2020-A-060**

Subject: Apron Entrance AK between Lane 5 and 6 - Hot Water Chamber Abandoning

From: Airport Operations

Contact: Cedric Daros, cedric.daros@gtaa.com, (416) 776-5854


Date: 2020-09-21

The area between Lane 5 and 6 on the vehicle corridor near Apron Entrance AK will be temporarily changed to a construction zone for a period of approximately three (3) weeks commencing on Sept 28, 2020 @ 0700L. This will facilitate work involved in abandoning a hot water chamber.

As a result of this construction, the following restrictions will be put into place:

- Apron Taxilane 5 will be temporarily displaced to the North to accommodate code E aircraft
- Apron Taxilane 6 between the North/South Taxilane and start box 6B will be restricted to code C and smaller
- Gt C34/C34A Closed
- North/South taxilane crossing AK restricted Code C aircraft or smaller
 - Aircraft up to Code E may still use AK to/from Lane 5 or North/South taxilane
- Gt C34 Tail-of-stand road will be relocated onto Gt C34
- Connecting corridor between Gt 139-C33 will be closed. Vehicles must find alternate routing to cross. Vehicles are not to cross the apron and transit around the immediate work area.

Please be aware of non-standard aircraft/vehicle movements in the area of Apron Entrance AK and Taxilane 5 and 6.



- Legend
- ██████████ BLACK-OUT EXISTING PAVEMENT MARKINGS
 - ▬▬▬▬▬▬ TEMPORARY VEHICLE CORRIDOR MARKING
SEE SD90C200
 - TEMPORARY TAXILANE CENTRELINE MARKINGS
SEE SD90C171
 - +—+—+— CONSTRUCTION BARRIER
SEE SD90C482

If you have any questions or concerns regarding this work, please contact Cedric Daros, cedric.daros@gtaa.com