

Advisory # **2023-A-006**

New Apron Taxilane Startboxes

From: Airport Operations; Airside Coordination

Contact: Cedric Daros, cedric.daros@gtaa.com, 416-776-5854


Date: 2023-04-04

In an effort to streamline apron operations, the following additions to the Apron paint markings are set to take effect on Friday April 20, 2023, at **0901Z**, referencing the release of the CAP:

- Along Terminal 3 Taxilane 1S, the activation of new Start Boxes "1SA" and "1SB".
- Along the Terminal 3 North/South Taxilane, the activation of new Start Boxes "T3A", "T3B", "T3C" and "T3D".
- Along the Terminal 1 North/South Taxilane, the activation of new Start Boxes "T1A", "T1B", "T1C", "T1D" and "T1E".
- Along the Terminal 1 East/West Taxilane, the activation of new Start Boxes "T1F", "T1G", "T1H", "T1J", and "T1K".
- Along the Terminal 1 Hold East/West Taxilane, the activation of new Start Boxes "T1L", "T1M".


Use of these start boxes will add an additional safeguard to maintain aircraft clearance distances during disconnect, while also aiding in reducing radio frequency congestion.

Larger format maps of locations can be referenced in the document "G02 - Apron Taxilane Restrictions – 2022-12-06" available upon request.




T3A, Int. Hold Line South of AT,
 abeam B15

T3B, Int. Hold Line North of AJ,
 T3C, Int Hold Line South of AJ



T3D, Int. Hold Line North of AK,
 T1A, Int. Hold Line South of AK

T1B, Int. Hold Line North of AL,
 T1C, Int. Hold Line South of AL



Toronto Pearson Advisory
New Apron Taxi Lane Startboxes