



**Advisory # 2023-A-014**

**T1 Apron Concrete Slab Replacement – AL Apron Intersection**

**From:** Airport Operations – Airside Coordination

**Contacts:** Cedric Daros, cedric.daros@gtaa.com, 416-432-5518

**Date:** 2023-05-18

Approximately 52 concrete slabs on the apron area between the intersections of AL and AK, require rehabilitation. This will require 4-phases of construction to replace these slabs, with several temporary changes being implemented on the apron to accommodate this work.

The first phase of work impacts the intersection of AL, and the western radius of Taxilane 7 and 8 along the North/South Taxilane. This work includes the following impacts:

- **May 23, 2300, until June 24, 2300** - 32 calendar days with weather days.
- Stand 143 downgraded to 777-200LR or smaller.
- AL intersection closed.
- Deviated taxilane radius between Stands 142 and Startbox 7B, Code E or smaller.
- AK intersection will be used for access to lanes 7/8.
- Inset lighting on North/South/East/West Taxilane will not be available.
- Connecting and Outer vehicle corridors crossing AL and lanes 7/8 closed.
- Temporary "S" Transition Taxilane added between Startbox 8C and 7B, Code E or smaller.
- Blast fence added to enable safe daytime work.

Please be aware of non-standard movements by aircraft, vehicles, and construction traffic in the vicinity of AL and use caution.

If you have any questions or concerns regarding this work, please contact Cedric Daros using the above contact information.

**Phase 1, May 23-June 24**

