



Supersedes: 2020-D-011

Directive 2021-D-002

Subject: Reopening Runway 06R/24L

From: Airport Operations

Contact: Manager Operations – Airside, ZZL-ManagerOperationsAVS@Gtaa.com, 416-776-1102

Date of Issue: 2021-04-21

Effective Date: 2021-04-22

Effective April 22, 2021 Runway 06R/24L will reopen along with all associated high speed taxiways south of Runway 06L/24R. This will include Taxiway Yankee (Y) between Runway 06R/24L and the south Skyservice FBO. Reactivation measures include the following:

- i. All runway and taxiway lights will be re-energized.
- ii. NOTAM's in relation to the surface closure are set to expire at 19:00L(23:00Z) April 22, 2021.
- iii. All visual aids (e.g. red obstruction lights, illuminated Runway closure markers and physical barricades) will be removed. Applicable airside guidance signs will be uncovered and reactivated.

Normal runway operations will resume at 19:00L(23:00Z) on April 22, 2021.

A handwritten signature in blue ink, appearing to read "Craig Bradbrook".

Craig Bradbrook
Chief Operating Officer, Airport Operations